




Horizon has recently received reports from customers experiencing issues with Dynamite Mach 2.19T engines. Specifically, customers have told Horizon that the backplate on their Dynamite Mach 2.19T is binding when Traxxas Ez-Start and pull start mechanisms are installed. Horizon has investigated and identified a tolerance issue for a small quantity of backplates during manufacturing.

Horizon has updated current stock physically stamping corrected backplates and marking each product box with a sticky dot to help customers know that their product has been corrected (see image).



Horizon has replacement backplates on hand to provide to customers who are experiencing this issue.

If you have had difficulty when trying to install your Dynamite Mach 2.19T and would like to request an updated backplate, please review and follow the instructions below.

- [Click here](#) for request form with instructions.
- Horizon will pay for ground shipping within the United States and Canada.
- Consumers outside the US and Canada should contact their local retailer or distributor. International distributors may be found [here](#).
- You may also e-mail the Horizon Hobby Product Support team. Please make sure "DYN0700 Backplate Request" is contained in the subject line and include your shipping address and daytime phone number. Click [here](#) to email product support.
- If you have any questions, you can call Horizon Hobby Product Support at 877-504-0233